

TO: J. P. Fundersol

S-Oxv Balt  
5/14/74

SWANN PARK SOIL ANALYSIS

<u>SAMPLE LOCATION</u>	<u>ARSENIC WT %</u>	<u>SAMPLE LOCATION</u>	<u>ARSENIC WT %</u>
S-1	0.07	S-18	0.008
S-2	0.07	S-19	0.05
S-3	0.04	S-20	0.04
S-4	0.23	S-21	0.02
S-5	0.04	S-22	0.14
S-6	0.11	S-23	0.06
S-7	0.05	S-32	0.02
S-8	0.05	S-33	0.02
S-9	0.03	S-34	0.015
S-10	0.04	S-35	0.018
S-17	0.05	S-36	0.014

Sample taken Sept. 27, 1973

0.01% Arsenic is normal for Baltimore area.

All of the above results are substantially lower than the tests of two years ago, with the exception of sample S-4 and S-22. This is in spite of the fact that production has increased substantially during the same period.

E.F. Hawkins  
Tech. Supv. - Baltimore Plant  
5/14/74

cc: E. E. Cox, Jr.  
G. F. Lawn

IRNMT0003882

SP20