

9404

7/3/69

~~waters from occasional washout of equipment drummed  
& "eventually dumped onto the ground well back  
from the river"~~

9/19/72

internal memo - dump may be leaching into river  
contains DDT, chromium residue & copper salts

9/21/72

internal ① bottom mud of river adj to plant ~ 1970  
1.2 → 3.4% arsenic; 0.3 → 1.86% chlorinated organics (DDT)  
150 - 2800 ppm chromium

② Swan Park → arsenic trioxide (playground)

5/76

~~soil~~ samples from dump area (soil) arsenic, lead,  
mercury, aldrin, chlordane, dieldrin, kepone,  
DDD, DDE & DDT, mirex, ~~nitrophenol~~ parathion

5/17/76

re 5/12 mtg w/ state cutoff arsenic lead than  
500-1000 ppm - cover dump & leave in place  
2 monitoring wells maintained by State but installed  
by BLD

3/24/76

River mud: Arsenic 610 → 11800 ppm; Kepone 4-36 ppm  
Copper 8-280 ppm; Chrome 9-53 ppm; Lead % 0.04 → 0.66  
Oil & Grease % 0.60-7.39 ranges 3-24"

3/4/76:

Mercury 1.0 → 222.0 ppm